ROY COOPER Governor MICHAEL S. REGAN Secretary BRIAN WRENN Director



August 18, 2020

#### CERTIFIED MAIL: 7019 0700 0000 8867 4575 RETURN RECEIPT REQUESTED

American Zinc Products, LLC Attn: Tim Basilone 4955 Steubenville Pike, Suite 405 Pittsburgh, Pennsylvania 15205

# CERTIFIED MAIL: 7019 0700 0000 8867 4742 RETURN RECEIPT REQUESTED

American Zinc Products, LLC Attn: Kobus DeWet 484 Hicks Grove Road Mooresboro, North Carolina 28114

Subject:

NOTICE OF VIOLATION (NOV-2020-PC-0369)

American Zinc Products, LLC

NPDES Individual Stormwater Permit NCS000562

Rutherford County, North Carolina

Dear Mr. DeWet and Mr. Basilone:

On July 1, 2020, Isaiah Reed from the Asheville Regional Office of the Division of Energy, Mineral and Land Resources (DEMLR or Division), conducted a compliance inspection for the American Zinc Products, LLC facility located at 484 Hicks Grove Road, in Rutherford County, North Carolina. A copy of the Compliance Inspection Report is enclosed for your review. The subject facility is covered by NPDES Individual Stormwater Permit NCS000562. Permit coverage authorizes the discharge of stormwater from the facility to receiving waters designated as the Broad River, a Class C waterbody in the Broad River Basin.

As a result of the compliance inspection, the following permit condition violations are noted:

### 1) Stormwater Pollution Prevention Plan (SPPP)

The provided site plan was found to be incomplete and lacked requirements found in Part II, Section A, 1(c) of the Permit.

#### 2) Analytical Monitoring

Analytical monitoring has not been conducted and recorded in accordance with permit requirements found in Part II, Section B, Tier 1, Tier 2, and Tier 3 response actions.

#### 3) Secondary Containment

Secondary containment has not been provided and maintained in accordance with Part II, Section A, 2(b) of the Permit.



#### **Tier 3 Required Actions**

In accordance with Part II, Section B, Tier 3 requirements, the permittee is required to conduct analytical monitoring, for all parameters, at the inlet to Basin 1 where the stormwater pipe discharges to the energy dissipater. This monitoring shall occur at a minimum of once every seven (7) calendar days to begin on the date of receipt of this Notice and to continue for a period not less than three (3) months from the date of receipt of this Notice. Be advised that this monitoring shall be done separately and in addition to the investigative monitoring conducted pursuant to Tier 2 response actions.

#### Requested Response:

You are asked to respond to this office, in writing, within 30 calendar days from receipt of this Notice. Your written response should include a reasonable explanation as to why the aforementioned violations have occurred as well as a Plan of Action to prevent these violations from recurring.

Thank you for your attention to this matter. This office is considering sending a recommendation for enforcement to the Division Director regarding these issues. Your above-mentioned response to this correspondence will be considered in this process. This office requires that the violations, as detailed above, be properly resolved. These violations and any future violations are subject to a civil penalty assessment of up to \$25,000 per day for each violation. Should you have any questions regarding these matters, please contact Isaiah Reed or myself at (828) 296-4500.

Sincerely,

Stanley E. Aiken PE<sub>GA</sub> Regional Engineer

Land Quality Section

Enclosure:

**Compliance Inspection Report** 

ec: Alaina Morman, Environmental Specialist <u>alaina.morman@ncdenr.gov</u>

Jeff Menzel, Environmental Specialist jeff.menzel@ncdenr.gov

Annette Lucas, Stormwater Program Manager annette.lucas@ncdenr.gov

Toby Vinson, DEMLR Section Chief toby.vinson@ncdenr.gov

Stormwater Program File

## **Compliance Inspection Report**

Permit: NCS000562 SOC:	Effective: 04/30/18 Effective:	Expirati Expirati		03/31/23	Owner: America Facility: America	an Zìnc I	Products, LLC	
County: Rutherford					484 Hic	cks Grov	e Rd	
Region: Asheville					Moores	boro NC	28114	
Contact Person: James D H	farris-	Title:				Phone:	828-919-3139	
Directions to Facility:								
System Classifications:								
Primary ORC:			Cert	ification:		Phone:		
Secondary ORC(s):								
On-Site Representative(s):								
Related Permits:								
Inspection Date: 07/01/2020 Entry Time 09:00AM		)9:00AM		Exit Time: 02:30PM				
Primary Inspector: Isaiah L.	Reed				!	Phone:	828-296-4614	
Secondary Inspector(s):								
Alaina Morman								
Reason for Inspection: Routine				Inspection Type: Compliance Evaluation				
Permit Inspection Type: St	ormwater Discharge, Ind	dividual						
Facility Status:	oliant Not Compli	ant						
Question Areas:								
Storm Water								

(See attachment summary)

Permit: NCS000562

Owner - Facility: American Zinc Products LLC

Inspection Date: 07/01/2020

Inspection Type: Compliance Evaluation

Reason for Visit: Routine

#### Inspection Summary:

On July 1, 2020 this facility was inspected for complaince. I met with Charles Howell and Shannon Andrews on site. During the inspection, the following items were noted:

- 1) Secondary containment was not provided for an above ground storage container located next to the office building, the permittee shall immediately begin efforts to provide adequate secondary containment for all bulk storage of liquid materials on site as outlined in the NCS000562 Individual Stormwater Permit.
- 2) The secondary containment for hazardous waste storage was damaged and cracked. The permittee shall immediately begin efforts to repair all containment structures on site to provide adequate secondary containment as outlined in the NCS000562 Individual Stormwater Permit.
- 3) The site plan was found to be incomplete and did not meet the requirements of the permit. the permittee shall immediately begin efforts to update, review and submit an accurate site plan as outlined in the NCS000562 Individual Stormwater Permit, including all stormwater infrastructure.
- 4) The Containment around the Solids storage located at basin one was found to be incorrecty installed, the permittee shall immediately begin efforts to address, inspect and repair all containment devices utilized on site to assure proper function and operation as outlined in the NCS000562 Individual Stormwater Permit.
- 5) After reviewing the analytical data provided on site, it was determined that the permittee has failed to implement all required actions in response to Tier 1, 2, and 3 requirements. The permittee id directed to immediately begin implementing all responsive actions outlined in the Tier 1 and Tier 2 requirements as outlined in the NCS000562 Individual Stormwater Permit. Be advised that this requirement includes Identifying and evaluating all possible causes of benchmark exceedances, this includes but is not limited to: investigative monitoring to evaluate where the source of the exceedance may be coming from. Please refer to the enclosed Notice of Violation for further requirements.

In accordance with Part II, Section B, Tier 3 requirements, the permittee is required to conduct analytical monitoring, for all parameters, at the inlet to Basin 1 where the stormwater pipe discharges to the energy dissipater. This monitoring shall occur at a minimum of once every seven (7) calendar days to begin on the date of receipt of this Notice and to continue for a period not less than three (3) months from the date of receipt of this Notice. Be advised that this monitoring shall be done separately and in addition to the investigative monitoring conducted pursuant to Tier 2 response actions.

If you have any questions, please contact this office at (828) 296-4614

Permit: NCS000562

Owner - Facility: American Zinc Products LLC

Inspection Date: 07/01/2020

Inspection Type : Compliance Evaluation

Reason for Visit: Routine

Stormwater Pollution Prevention Plan	Yes No NA NE			
Does the site have a Stormwater Pollution Prevention Plan?				
# Does the Plan include a General Location (USGS) map?				
# Does the Plan include a "Narrative Description of Practices"?				
# Does the Plan include a detailed site map including outfall locations and drainage areas?				
# Does the Plan include a list of significant spills occurring during the past 3 years?				
# Has the facility evaluated feasible alternatives to current practices?				
# Does the facility provide all necessary secondary containment?				
# Does the Plan include a BMP summary?				
# Does the Plan include a Spill Prevention and Response Plan (SPRP)?				
# Does the Plan include a Preventative Maintenance and Good Housekeeping Plan?				
# Does the facility provide and document Employee Training?				
# Does the Plan include a list of Responsible Party(s)?				
# Is the Plan reviewed and updated annually?				
# Does the Plan include a Stormwater Facility Inspection Program?				
Has the Stormwater Pollution Prevention Plan been implemented?				
Comment: See summary for more information.				
Qualitative Monitoring	Yes No NA NE			
Has the facility conducted its Qualitative Monitoring semi-annually?				
Comment:				
<u>Analγtical Monitoring</u>	Yes No NA NE			
Has the facility conducted its Analytical monitoring?				
# Has the facility conducted its Analytical monitoring from Vehicle Maintenance areas?				
Comment: Analytical monitoring not conducted in accordance with Tier 2 requirements.				
Permit and Outfalls	Yes No NA NE			
# Is a copy of the Permit and the Certificate of Coverage available at the site?				
# Were all outfalls observed during the inspection?				
# If the facility has representative outfall status, is it properly documented by the Division?				
# Has the facility evaluated all illicit (non stormwater) discharges?				
Comment:				